



④-2芳賀支部(13-21)



9月10日 06:09:34  
加増橋現在異常なし



9月10日 06:19:32  
開運橋現在異常なし



9月10日 06:19:32  
五行川若橋付近の状況写真です。



④-2芳賀支部(13-21)



神明橋  
 9月10日 06:47:35  
 神明橋現在状況

---



---



---



---



芳賀町芳志戸  
 9月10日 07:05:38  
 五行川 両郡橋

---



---



---



---



大川 西原橋  
 9月10日 07:07:50

---



---



---




---





④-2芳賀支部(13-21)



河川の出水状況写真  
9月10日 07:07:58



河川パトロール五行川、行屋川合流点  
9月10日 07:12:17



行屋川 静風橋付近  
9月10日 07:21:01



④-2芳賀支部(13-21)



9月10日 07:31:26  
稲毛田 大川 下久根橋



稲毛田  
9月10日 07:37:59  
大川 下久根橋北の橋、水路に決壊




9月10日 07:40:34  
深沢川 石沢橋付近




④-2芳賀支部(13-21)



9月10日 07:43:51  
報告



9月10日 07:44:52  
道下橋 水位状況



9月10日 07:50:15  
湯前橋から下流を撮影





④-2芳賀支部(13-21)



9月10日 07:51:45  
深沢川 石沢橋付近




芳賀町芳志戸  
9月10日 07:52:28  
五行川 秋場橋



五行川花の木橋付近出水状況  
9月10日 07:53:48



④-2芳賀支部(13-21)



9月10日 07:55:48  
仲の車橋 水位状況




小貝川 小貝川大橋  
9月10日 07:56:30  
小貝川大橋です。





9月10日 07:56:33  
大川 田島橋

④-2芳賀支部(13-21)



9月10日 07:57:41  
高畦橋から下流を撮影



桜川 地藏橋  
9月10日 08:07:19  
桜川 地藏橋です




9月10日 08:09:13  
五行川長瀬橋



④-2芳賀支部(13-21)



9月10日 08:09:46  
上稲毛田 大川 弁天橋



小貝川 小貝橋  
9月10日 08:09:53  
小貝川 小貝橋です



9月10日 08:11:35  
小宅川 あづま橋

